

# **TECHNICAL DATA SHEET**

Type of coating PA - POLYESTER POWDER COATINGS

Color RAL 5003

**Symbol** PA111/0/2224/07

Surface Smooth
Gloss Gloss

Characteristics - Outdoor, industrial application

- Good weather resistance

Good chalking resistanceVery good covering power

Decorative and metallic effect

- Very good mechanical resistance

Applications Agricultural machinery, furniture and garden tools, machine casings, mailboxes, etc.

Powder properties Particle size (Malvern) Fine powder suitable for electrostatic spray (corona) and tribocharging (tribo).

**Density (g/cm³)** 1,534 ISO 8130-2

Theoretical coverage (m²/kg) ~9 by the film thickness 70 µm and 100 % use of powder coating.

Storage stability 24 months from the date of production, in the original, unopened package, keep

away from heat sources, in the temperature of  $5-25^{\circ}$ C, protect from moisture. No direct sun exposure. The product should be stay at ambient temperature (paint

shop) 12h before use.

85 ±5 GU

Coating filmThicknessrecommended 70-90μm - max. 120μm

steel panel

Gloss (60°)

tested in lab conditions on:

ISO 2813<sup>1</sup> VISUAL<sup>2</sup>

ISO 2808

ISO 1520

ISO 2815<sup>3</sup>

Cross cut 0

ISO 2409

Mandrel bending <5 mm ISO 1519

Erichsen cupping >5 mm

Impact resistancefront>50 kg/cmISO 6272-1reverse>50 kg/cm

Buchholz hardness >80

Pencil hardness 2H

ISO 15184<sup>3</sup>

(1) applies to smooth and no metallic coatings film (2) applies to structural and metallic coatings film (3) not applicable structural coatings film

Eko-Color Sp. z o.o.
St. Sucharskiego 2, 77-100 Bytów, Poland
Tel. +48 59 822 22 22, e-mail: info@eko-color.pl

Version: 1.0 Date of version: 24.11.2020



# TECHNICAL DATA SHEET

# Surface pretreatment

- The overall quality of the coating film depends on the type and quality of the pretreatment.
- Surfaces must be dry, degreased and free from rust and other contaminants.
- In order to improve coating adhesion to the surface and improve resistance it is recommended: aluminium - chromating, chrome-free pretreatment or anodic pretreatment.
   steel and galvanized steel - individual choice of surface pretreatment (e.g. phosphating).
- However, in order to achieve optimum results, you must follow the instructions and recommendations of the pretreatment material manufacturer.

### **Application**

- Electrostatic gun corona (recommended voltage 60 kV) or tribo gun.
- Application parameters depend on the geometric shapes of the detail and the film thickness to be reached.
- Responsibility for the correct application parameters lies on the coating applicators.
- Despite careful production methods, slight deviation of color and effect between the different manufacturing batches may occur (typical for powder coatings).
- Various application parameters may cause color/effect changes.
- Proper grounding of application equipment and coated elements helps to keep repeatability of the obtained color/effect.
- It is recommended to do the entire order on the same equipment, with the same application parameters and using powder coating from one production batch.
- Not be mixed with other powder coatings.
- Control the air speed during application of powder coatings.
- Keep the appropriate distance: the gun coated elements.
- Keep a uniform thickness of coating.

#### **Curing conditions**

- Curing time recommendation in a convection oven:

## 180°C/10min. 170°C/15min.

(object temperature)

- Must be strictly observed parameters of stoving the coating film to ensure that the full mechanical and chemical properties.
- Suitability of the product for stoving in gas ovens and radiant ovens should be verified may be a significant difference in color perform a comparative test with the standard color (please contact us for details).

#### **Approvals**

Comments

- The powder coatings are in compliance with 2011/65/EC and 2015/863/EC (so called ROHS).
- Heavy metal and TGiC free.

# Technical recommendations

- In the case of cleaning powder coated surfaces it is necessary strict compliance with the Technical recommendations 01: Cleaning of powder coated surfaces.

- To print, to glue, to label, to laminate with foil, over-coating or any other post-treatment, some preliminary testing is recommended.
- Powder-coated details should be packaged after being completely cooled down to ambient temperature, into appropriate packaging materials previously tested by the user.
- Packaged details should be stored under cover to avoid condensation, which may result in traces on the finished coating

#### **Safety Data Sheet**

POLYESTER POWDER COATINGS PA, PA/FP - TI

## Edition / date

2.1 / 2023-05-10

The above values may vary depending on the type of surface pretreament, color, gloss, texture, etc.

All informations included in this card are based on our experience and actual knowlegde and do not release the user from carrying out their own tests. If in doubt please contact us for details. Having no influence on the use and application conditions, we can take responsibility only for the quality of any the product and ensure that it fits to our standards. This Technical Data Sheet is revised periodically. EKO-COLOR reserves the right to change specifications without notice.

If necessary, our sales department will confirm the validity of this document.

Version: 1.0 Date of version: 24.11.2020

